SECRET

Copy 6 of 6

7 August 1958

MINORANIAN FOR

Special Assistant to the Director for Flaming and

Development and Deputy Director, DPS

THRU

Director of Development and Procurement, DPS

25X1A 25X1A SUBJECT

	Field	Trip	of	Dr.	R.	Scott	and.	
to Detachments.								

1. Dr. R. Scott and the undersigned will be at Detachment B from 12 August to 16 August. At Detachment C from 19 August to 26 August. Items which will be covered during this time are stated in the following paragraphs.

2. Quality Control

*

- A. Present and discuss Headquarters Photo Tesm trip report with Detachment Commanders.
- B. Present and discuss with Detachment Commander Dr. Scotts letter to Mr. Bissell. Letter is report of meeting with Hycon factory personnel, Detachment Photo Supervisors and Dr. Scott in Washington, D. C. 8 July 1958.
- C. Determine reason for non-compliance with SOP 7 dated 17 March 1957; Subject: Photo Analysis-S Curve. HOTE: This SOP was written at the Detachments by numbers of the Headquarters Photo Team. All detachments acknowledged receipt of Analysis Hits in early April 1958.

D. If necessary indoctrinate per	sonnal in analysis kits.
----------------------------------	--------------------------

25X1A 25X1A

2. Study test mission take (See 1428 (OUT 81808) and 1470 (OUT \$1878)) to determine quality and to isolate factors

Approved For Release 2002/10/29: CIA-RDF 63-00313A000600010030-2

6 same

- F. Discuss quality discrepencies noted in missions now at HTA.
 - G. Check optics of configurations.
- H. Determine cause and solution to fogging of Driftsight and Tracker bubble.

3. Configurations, General

- A. Discuss configuration malfunctions and action being taken to remedy them.
 - B. Check spare parts status.
- C. After appraisal of all facts, determine realistic maximum mission rate for B configuration.

25X1A	
25 Χ 1Δ	

- D. Check and remedy Tracker, Hand Control and Driftsight Problems. NOTE:

 P & E, will handle this item at Detachment B. Dr. Scott and I will survey Detachment C to establish need for at that Detachment.
- E. Assure shipping of one (1) 24" camera from Detachment B to Detachment C via M and O. <u>MOTE:</u> Detachment B has 10 cameras, Detachment C 8 cameras. During last visit of Photo Team, Detachment B was instructed to send camera to M and O but to date have not complied.
- F. State type data which should be included in all TWX mission reports.

4. Personnel

- A. Chserve attitude and technical ability of personnel.
- B. Through Photo Supervisor get names of personnel who would possibly sign on for enother year.

5. Film

- A. Check stocks to determine if film is being properly rotated.
 - B. Check area for empty spools and boxes.
 - C. Check status of 70 MM dupe material and spools.

A. Check 70 MM processor and spare parts.

B. Observe _____operations, noting condition of processors, techniques used and caliber of personnel.

7. System 4

25X1A

A. Ca request by _____ we will offer our services at Detachment B on problems relating to the System 4 camera.

25X1A

SA/PD/DCI: bas
Distribution:
Orig. - SA/PD/DCI - Dep. Dir., DPS
2. - Dir. of D and P, DPS
3. - Dir. of OPS, DPS
4. - (copy to Dr. Scott)
6. - Chrono (Contracts)

Approved For Release 2002/10/29 : CIA-RDP63-00313A000600010030-2